25X1C

CENTRAL INTELLIGENCE AGENCY
PHOTOGRAPHIC INTELLIGENCE DIVISION
PHOTOGRAPHIC INTELLIGENCE REPORT

CURRENT STATUS OF BOMBED BRIDGES IN NORTH-VIETNAM

CIA/PIR-65007 JULY 1965



WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 187 sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by laws

Declass Review by NIMA/DoD



25X1C



CIA/PIR-65007

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

CURRENT STATUS OF BOMBED BRIDGES IN NORTH VIETNAM

This Photo Intelligence Report is a continuing assessment of the status of bombed bridges in North Vietnam. The preliminary effects of the bombing of bridges was studied in CIA/PIR-5007/65, July 1965, where twenty-two bridges were studied.

The thirty-nine bridges included in this study are listed in numerical sequence in the enclosed table. Included within the table is information of the extent of damage to each bridge, compensative action by the North Vietnamese, and the date of photographic coverage. The bridges under study are located on the enclosed map by numbers coinciding with the numerical sequence of the enclosed table. (Figure 1, CIA/IAD/IB-P-624/65)

SECRET NO FOREIGN DISSEM

25X1C ~

25X1C SECRET

TABLE OF BOMBED BRIDGES IN NORTH VIETNAM

CIA/PIR-65007

								25X1D
NO	<u>).</u>	NAME	*	TYPE	ROUTE	LOCATION	STATUS	COMPENSATIVE ACTION
	L.	Ninh Binh	. 1	C _.	10	201540N-1055920E	One spen dropped	New approach constructed Float bridge sections near- by
, :	2.	Dong Phong T	Thuong	C	1	195836N-1055005Е	One span dropped, two damaged	Float bridge upstreem
	3•	Thenh Hos		·C	1	195012N-1054765E	Repaired	Trafficable for vehicles, track replaced
	4.	Thi Long		R		193150N-1054250E	Abutment damaged, approach damaged	Repaired
	5.	Qui Vinh		R		191545N-1054120E	One span destroyed, approach damaged	New approach with spur track, piers in river
	6.	Phuong Can	d d	·H	. 1	191415 N- 1054223E	Repaired	Temporary deck spen, floating bridge downstream
	7.	Ly Nhan	\$	H	1	190022N-1053530E	Two spans destroyed, two spans demaged	Ferry landings improved, pontoon ferry upstreem
	8	Dien Chau	,	R		185820N-1053455E	Two spans destroyed, approach damaged	abutment repaired
	9.	Tem De	ř . : . :	C	1	185654 N- 1053915E	Two spans destroyed, one span damaged	Ferry site improved slightly, ferry located upstream

^{*} NOTE: R-Reil Bridge, H-Highway Bridge, C-Combination Bridge

CIA/PIR-65007

SECRET
NO FOREIGN DISSEN
25X1C

TABLE OF BOMBED BRIDGES IN NORTH VIETNAM - Page 2

25X1D

MSN DATA

			•				
	NO.	NAME +	*TYPE RO	DUTE LA	CATION	STATUS	COMPENSATIVE ACTION
	10.	Ninh Xs	н -	1 183030	ON-1054340E One	e span destroyed	Improved low water ford
	11.	Tho Son	H	1 48272	2N-1054643E One	e span destroyed	Ferry site improved, possible construction material nearby
	12.	Xom Gia	н	1 18250	2N-1054830E One	e span dropped	No change-ferry site '
S,	13.	Kinh Thuong	H	182040	N-1055600E Th	ree spans destroyed	None
	14.	Ha Tinh	H	1 18190	7N-1055504E De:	stroyed	Existing ferry site
	15.	Tho Ngos	H	18141		ree spans stroyed	New ferry crossing
	16.	Kimnec	H	181350	ON-1060220E Mod	derate demage	Repaired
	17.	Tu Dung	H	1 18125	BN-1060650E Two	o spans destroyed	Ferry site slightly improved
	18.	Thanh Yen	H .	17381	N-1063125E Two	o spans destroyed	Light framework replacing destroyed spans, ferry site improved
	19.	Xom Phuong-West Xom Phuong-East	H H			o spans destroyed paired	None Four destroyed spans replaced

^{*} NOTE: R-Rail Bridge, H-Highway Bridge, C-Combination Bridge

SECRET

CIA/PIR-65007

	eronet			•		
	SECRET No. CORFERN DISSEN	L d	TA	BLE OF BOMBED BRIDG	GES IN NORTH VIETNAM -	Page 3
· 1/2		25X1C		*	•	25X1D
NO.	NAME	*TYPE	ROUTE	LOCATION	STATUS	COMPENSATIVE ACTION
20.	Dong Hoi	· į H	1	172725N-1063745E	Two spans destroyed	Ferry
21.	My Duc	H		171345N-1064210E	One span destroyed, one span dropped	Light footbridge down- streem
22.	Ban Pleng Hom	Н	7	192210N-1041330E	Two spans destroyed, one span damaged	Ford reactivated
23.	Ban Ca Nan	Н	7	192038N-1041615E	Destroyed	Newly constructed ferry site
24.	Khe Kien	4- H	7	191621N-1042117E	Destroyed	Causeway approach improved, footbridge connecting piers
25.	Cha Lum	e H	7	190740N-1044430E	Destroyed	Ford Reactivated
26.	Phuc Thiem	H H	7	185771N-1053420E	Destroyed	Approach improved, light pier framework, probable construction material
. 5	4			• <u></u>		nearby, new footbridge downstream
27.	Vinh Area	Н	. 15	‡84010N-1053920E	One span destroyed, one span dropped	By-pass roads to small bridge upstreem

^{*} NOTE: R-Rail Bridge, H-Highway Bridge, C-Combination Bridge

SECRET

CIA/PIR-65007

	SECRET NO FOREIGN DISSEM		TABLE	OF BOMBED BRIDGES	IN NORTH VIEINAM - Pag	e 4
	25X1C	4		1	A3	<u>25X1</u>
NO.	NAME	*TYPE	ROUTE	LOCATION	STATUS	COMPENSATIVE ACTION
28.	Kim Cuong	H	8 ;	182635N-1051430E	One span destroyed	Ford
29.	Near Kim Cuong	Н	8	182645N-1051500E	One span destroyed, two spans damaged	Ford
3 0.	Trai Hoi	C	·15	182137N-1053700E	One span destroyed; one span demaged	Abutment and trestle reconstruction
31.	Sen Dinh	H	82	182403N-1054341E	Destroyed	New by-pass road with new bridge
32:	Bai Duc Thon-NW	H	12	180405N-1054930E	Repaired	Piers and light decking
33.	Le Khe Thon	R ∉	:	180358N-1054925E	Destroyed	Approach fightly repaired
34.	Bei Duc Thon	,C	12	180325N-1055020E	Approach destroyed, truss damaged	Ford approach repaired and ford reactivated, new unimproved road by-passing
35•	Xom Ca Trang-North	h H	12	175715N-1054855E	Destroyed	Ford approach repaired
36.	Xom Ca Trang-South	h H	12	175715N-1054855E	One span destroyed	New ford approach

^{*} NOTE: R-Reil Bridge, H-Highway Bridge, C-Combination Bridge

25X1C

SECRET NO FOREIGN DISSEN 25X1C

TABLE OF BOMBED BRIDGES IN NORTH VIETNAM - Page 5.

		•			A 1
NO.	NAME	*TYPE ROUTE	LOCATION	STATUS	COMPENSATIVE ACTION
37.	Xom Thanh	H 12	175430N-1054930E	Abutment damaged, span dropped	Ford reactivated
38.	La Trong	H 12"	175100N-1054820E	Destroyed	Ford reactivated
39.	Don Bai Dinh	H 12	174540N-1054640	Destroyed	Ford reactivated, new approach to new crossing site

R-Rail Bridge, H-Highway Bridge, C-Combination Bridge

25X1C

25X1D

25X1C

SECRET

CIA/PIR-65007

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

REFERENCES

PHOTOGRAPHY

25X1D

MAPS OR CHARTS

Annotated Locator Map (Indochina Terrain and Transportation 50252 1-65) - UNCLASSIFIED

REQUIREMENT

CIA, C-RR5-82,800

CIA/IAD PROJECT

30067-6

SECRET

25X1C

